View NSN Online: https://aerobasegroup.jp/nsn/8010-00-286-9080

CHEMRAY COATINGS CORPORATION -- PAINT, BOOT-TOPPING -- 8010-00-286-9080
========== Product Identification ==========

Product ID:PAINT, BOOT-TOPPING
MSDS Date:01/01/1987
FSC:8010
NIIN:00-286-9080
MSDS Number: BDTZB
=== Responsible Party ===
Company Name:CHEMRAY COATINGS CORPORATION
Address:209 MICHIGAN AVE.
City:KENILWORTH
State:NJ
ZIP:07033
Country:US
Emergency Phone Num:201-245-1111
CAGE:OBRN9
=== Contract
or Identification ===
Company Name:CHEMRAY COATING CORP
Address:209 N MICHIGAN AVE
Box:City:KENILWORTH
State:NJ
ZIP:07033
Country:US
Phone:201-245-1111
CAGE:33832
Company Name:CHEMRAY COATINGS CORP.
Address:209 N. MICHIGAN AVE.
Box:NA
City:KENILWORTH
State:NJ
ZIP:07033
Country:US
Phone:800-924-9300
CAGE:OBRN9

========== Composition/Information on Ingredients ==========

Ingred Name:PIGMENTS
Fraction by Wt: 33%

Ingred Name:ALKYD RESIN
Fraction by Wt: 51%

Ingred Name:MINERAL SPIRITS 66

Fraction by Wt: 13%
ACGIH TLV:120 PPM

Ingred Name:LEAD COBALT DRIERS (OSHA PEL FROM 29CFR 1910.1025)
OSHA PEL:0.05 MG/M3 (PB)
ACGIH TLV:0.15 MG/M3(PB); 8990

Ingred Name:ZINC CHROMATE
CAS:13530-65-9
RTECS #:GB3290000
Fraction by Wt: 11%
OSHA PEL:0.1 MG/M3 (CRO3)
ACGIH TLV:0.01MG/M3(CR)A1;9192

========== Hazards Identification ==========

Effects of Overexposure:EXCESSV INHAL MAY CAUSE HEADACH,DIZZ,UNCONSCIOUSNES.OR COMA.SKIN/EYE CONTCT:IRRIT, DRY OF SKIN.

=====
========== First Aid Measures ==========

First Aid:FUMES:REMOV FROM EXPOSR,RESTORE BREATHING.KEEP WARM. NOTIFY PHYSICIAN.SPLASH(EYES):FLUSH W/RUNNING WATER AT 15 MIN.TAKE TO DR.REMOV CONTAM CLOTHING.CONSULT PHYSICIAN.SPLASH(SKIN):WASH AFFECTED AREA W/ SOAP & WATER.

========== Fire Fighting Measures ==========

Flash Point:100F/38C PMCC
Extinguishing Media:CO*2,DRY CHEMICAL OR FOAM
Fire Fighting Procedures:WATR FOG MAY BE USED TO COOL C
LOS CONTNRS TO
PRVNT PRESSR(SU
Unusual Fire/Explosion Hazard:CLOS CONTNRS MAY EXPLOD WHN EXPOSED TO EXTREME HEAT.DO NOT APPLY TO HOT SURFACES.

========== Accidental Release Measures ==========

Spill Release Procedures:REMOV W/ABSORBENT MATERIAL, FLUSH W/WATER INTO RETAINING AREA OR CONTAINER.AVOID SPARKS, FIRE & HOT SURFACES. VENTILATE AREA.

========== Handling and Storage ==========

Handling and Storage Precautions:KEEP AWAY FR HEAT

,SPARKS,OR OPEN
FLAME. USE WITH ADEQUATE VENTILATION.AVOID PROLONGED OR REPEATED CONTACT WITH SKIN.
Other Precautions:DO NOT TAKE INTERNALLY.

========== Exposure Controls/Personal Protection ==========

Respiratory Protection:WHN SPRAYING USE NIOSH & MESA APPRVD.
Ventilation:LOC EXHAUST-SUFF.TO KP LEL & LOWST TLV BELO STATED LIMIT.(SU
Protective Gloves:F/PRLNG/REPEATD
Eye Protection:GOGGLES-SPLASH OR SPRAY
Other Protective Equipment:IMPERMEABLE APRON F/PROLNG OR REPEATED

CONTACT.
Supplemental Safety and Health
SPEC.FIRE FIGHT:BUILD UP & AUTO IGNITION WHEN EXPOS TO EXTREME HEAT.WEAR SELF-CONTAINED BREATHING APPARATUS. VENTILAT:MECH-FANS USING EXPLOSION PROOF MOTORS ONLY.

========== Physical/Chemical Properties ==========

HCC:F4
Boiling Pt:B.P. Text:315-390
Spec Gravity:1.16
Evaporation Rate & Reference:N-BUAC .1
Solubility in Water:NEGLIGIBLE
Appearance and Odor:BLACK LIQUID,NOT OBNOXIOUS
Percent Volatiles by Volume:58

==========
======= Stability and Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES
STRONG OXIDIZING AGENTS,STRONG ACIDS OR BASES
Stability Condition to Avoid:HEAT,SPARKS,OPEN FLAME & FIRE.
Hazardous Decomposition Products:THERMAL DECOMP.MAY YIELD CARBON MONOXIDE AND/OR CARBON DIOXI

========== Disposal Considerations ==========

Waste Disposal Methods:INCINERATE IN APPROVED FACILITY OR DISPOSE OF IAW LOC,STATE & FEDERAL REGULATIONS.DO NOT INCINERA

TE.CLOSED
CONTAINERS.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information t
o their
particular situation.