

CHRYSLER CORP. -- 1992151 -- 5910-00-076-5140

=====
Product Identification
=====

Product ID:1992151
MSDS Date:01/01/1985
FSC:5910
NIIN:00-076-5140
MSDS Number: BCXMG
=== Responsible Party ===
Company Name:CHRYSLER CORP.
Address:1200 CHRYSLER DR
Box:1718
City:DETROIT
State:MI
ZIP:48288-1718
Country:US
Emergency Phone Num:NONE
CAGE:JO988
=== Contractor Identification ===
Company Name:CHRYSLER CORP.
Address:1200 CHRYSLER DR
Box:1718
City:DETROIT
State:MI
ZIP:48288-1718
Country:US
CAGE:JO988
Company Name:CHRYSLER MOTORS
Address:1200 CHRYSLER DR
Box:1718
City:DETROIT
State:MI
ZIP:48288-1718
Country:US
Phone:313-956-5478
CAGE:12204

=====
Composition/Information on Ingredients
=====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)
CAS:1336-36-3
RTECS #:TQ1350000
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

=====
Hazards Identification
=====

E

Effects of Overexposure: ABSORBED THRU SKIN, LUNGS, INTESTINE. CAUSES CANCER, LIVER, KIDNEY, STOMACH, EYE, HEARING DISORDER (SUP DATA)

=====
First Aid Measures
=====

First Aid: EYES: FLUSH W/WATER IMMEDIATELY. SKIN: WASH W/SOAP IMMEDIATELY. INHAL: REMOVE TO FRESH AIR, GIVE ART. RESPIR. AS NEEDED. INGEST: GET MEDICAL ATTN. GIVE LARGE QTY OF SALT WATER, INDUCE VOMITING, BUT DO NOT MAKE UNCONSCIOUS PERSON VOMIT.

=====
Accidental Release Measures
=====

Spill Release Procedures: USE ABSORBENT & DIKES TO PREVENT RUNOFF. ISOLATE & NOTIFY PROPER AUTHORITIES.

=====
Handling and Storage
=====

Handling and Storage Precautions: STORAGE MUST FOLLOW RCRA REQUIREMENTS.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection: SUPPLIED AIR W/FULL FACEPIECE, HELMET OR HOOD
Ventilation: LOCAL EXHAUST
Protective Gloves: RUBBER-IMPERV
Eye Protection: GOGGLES, FACE SHIELD
Other
Protective Equipment: FULL CLOTHING TO PREVENT SKIN CONTACT
Supplemental Safety and Health
OVEREXPOS: CAN CAUSE FORMATION OF CYSTS, CAUSES STILLBIRTHS. IRRITATES EYES, NOSE THROAT.

=====
Physical/Chemical Properties
=====

HCC: Z3
Appearance and Odor: LIGHT STRAW-COLORED LIQUID, AROMATIC ODOR

=====
Stability and Reactivity Data
=====

STRONG OXIDIZERS

=====
Disposal Considerations
=====

Waste Disposal Methods: C

CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH
TEMPERATURE INCINERATION. ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professio
nal advice to verify and
assume responsibility for the suitability of this information to their
particular situation.