

HENRY W W CO -- HENRY 430 CLEAR THIN-SPREAD FLOOR TILE ADHESIVE -- 8040-01-261-4187

===== Product Identification =====

Product ID:HENRY 430 CLEAR THIN-SPREAD FLOOR TILE ADHESIVE

MSDS Date:12/01/1995

FSC:8040

NIIN:01-261-4187

MSDS Number: CCLYZ

=== Responsible Party ===

Company Name:HENRY W W CO

Address:5608 SOTO ST

City:HUNTINGTON PARK

State:CA

ZIP:90255-2629

Country:US

Info Phone Num:213-583-4961

/ FAX 213-582-8451

Emergency Phone Num:800-424-9300(CHEMTREC)/213-583-4961

CAGE:11761

=== Contractor Identification ===

Company Name:HENRY W W CO

Box:3001

City:LANCASTER

State:PA

ZIP:17604

Country:US

Phone:717-396-2328;717-396-2935

CAGE:11761

===== Composition/Information on Ingredients =====

Ingred Name:VM & P NAPHTHA (PER MSDS:MAY VARY DEPENDING ON SOLVENT
SUPPLIER)

CAS:64742-89-8

Fraction by Wt: 2%

Other REC Limits:NONE RECOMMENDED

Ingred Name:EXTRACTS, HEAVY NAPHTHE

NIC DISTILLATE SOLVENT
CAS:64742-11-6
RTECS #:PY8042000
Fraction by Wt: 24%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:300 PPM
ACGIH TLV:300 PPM

===== Hazards Identification =====

LD50 LC50 Mixture:NONE SPECIFIED BY MANUFACTURER.
Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:ACUTE:EYE:PROD/VAP MAY CAUSE
IRRIT,TEAR,REDNESS,BLUR VISION,CONJ.SKIN:BRIEF CONTACT MAY
CAUSE
IRRIT.PROL/REP MAY CAUSE
REDNESS,BURNING,DRYING,CRACKING.INHAL:MISUSE/USE W/INADEQU VENTI
MAY CAUSE RESP T RACT IRRIT,CNS EFFECTS.INGEST:MAY CAUSEGI
IRRIT,CNS EFFECTS.CHRONIC:INHAL:PERM BRAIN,NERVOUS SYS
DMG,ANEMIA,IRREG (SUP)
Explanation of Carcinogenicity:PER MSDS:CHRONIC OVEREXPO TO AROMATIC
PROCESS OILS IS REPORTED TO HAVE CAUSE SKIN CANCER IN RATS.
Effects of Overexposure:INHAL:IDDZ,WEAKNESS,FTG,NAU,HEAD.INEST:GI
IRRIT,NAU,VOMIT,DIARRHEA.SYMTOMS OF OVEREXPO
:NOSE/THROAT
IRRIT,DIZZNDRUNKENNESS,WEAKNESS,NAUSEA,HEADACHE.
Medical Cond Aggravated by Exposure:PRE-EXISTING EYE/SKIN/CENTRAL
NERVOUS SYTEM/RESP DISORDERS. TARGET ORGANS:NERVOUS SYSTEM,KIDNEYS.

===== First Aid Measures =====

First Aid:EYE:IMMED FLUSH W/PLENTY OF WATER FOR @LEST 15MINS.REMOVE
CONTACT LENSES.HOLD EYELIDS OPN.GET IMMED MED ATTN.SKIN:REMOVE
CONTAMIN CLOTH/SHOES.WASH THOROUGHLY W/SOAP/WATER.IRRIT PERSISTS
GET MED ATTN.I NH
AL:REMOVE TO FRESH AIR.BREATH DIFFICULT GIVE
OXY;STOP BREATH IMMED BEGIN ART RESP.KEEP WARM/QUIET.GET IMMED MED
ATTN.INGEST:GET IMMED MED ATTN.DROWSY/UNCONSC PLACE ON LEFT SIDE
W/HEAD DOWN.(SUPPLE)

===== Fire Fighting Measures =====

Flash Point:NA
Autoignition Temp:Autoignition Temp Text:NP
Lower Limits:NP
Upper Limits:NP
Extinguishing Media:USE EXTINGUISHING MEDIA APPROPRIATE FOR SURROUNDING
FIRE.
Fire Fighting Procedures:WEAR SELF-CONTAINED B

REATHING APPARATUS & FULL

PROTECTIVE FEAR. USE WATER SPRAY TO COOL FIRE-EXPOSED CNTNRS.
Unusual Fire/Explosion Hazard:WET MATL IS NOT COMBUSTIBLE.CLSD CNTNRS
MAY RUPTURE DUE TO PRESSURE BUILDUP.

===== Accidental Release Measures =====

Spill Release Procedures:WEAR PPE AS SITUATION WARRANTS.COVER SPILL
W/FLOOR ABSORBENT/OTHER INERT MATL.SCOOP MATL INTO DOT APPROVED
CNTNR;REMOVE TO SAFE PALCE TO DRY.KEEP PRODUCT OUT OF SEWERS/OPEN
BODIES OF WATER.U
SE CUATION -FLOOR MAY BE SLIPPERY.
Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.

===== Handling and Storage =====

Handling and Storage Precautions:USE/STORE IN COOL DRY WELL VENTI AREA
AWAY FROM INCOMP MATLS.KEEP OUT OF REACH OF CHILDREN.USE ONLY AS
DIRECTED ON LABEL.CLS CNTNR AFT EA USE.
Other Precautions:.DO NOT REUSE CNTNR.AVOID SKIN/EYE CONTACT.INITIALY
MAY BE POT ADVERSE IMPACT ON INDOOR AIR QUALITY WH/IN GEN WORKAREA
DURING INSTALL
ATION PROCESS-ADVISE BLDG MNGR/APPROPRIATE
PERSON.PERSONS SENS TO ODORS/CHEM ADVISE TO AVOID WORKAREA.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:WEAR NIOSH APPROVED RESP PROTECTION WHEN PEL OR
COMFORT LEVEL MAY BE EXCEEDED.
Ventilation:USE ONLY W/ADEQU VENTI.OPN DOORS/WINDOWS.PROVIDE SUFFI
MECH(GEN &/OR LOC EXHAU)VEVTI TO KEEP VAP LEVELS BEL OSHA PEL.
Protective Gloves:RUBBER GLVOES.
Eye Protection:GOGGLES TO PREVENT EYE CONTACT.
Ot
her Protective Equipment:SOURCE OF CLEAN WATER SHOULD BE AVAILABLE IN
WORKAREA FOR FLUSHING SKIN/EYES.WEAR IMPERVIOUS PROTECTIVE
CLOTHING.
Work Hygienic Practices:AVOID VAP BREATH,PROL/REP SKIN CONTACT.REMOVE
CONTAM CLOTH/SHOES;CLEAN WELL BEF REUSE.WASH WELL AFT HNDLG
W/SOAP/WATER.
Supplemental Safety and Health
HEALTH HAZ:HEART RHYTHM,BEHAVIORAL CHANGES. 1STAID:DON'T GIVE ANYTHING
BY MOUTH.DON'T INDUCE VOMIT UNLESS DIRECTED TO DO SO BY MED
PERSONNEL;VOMIT OCCURS SPONS KE

EP HEAD BEL HIPS TO PREVENT
ASPIRATION OF LIQ INTO LUNGS.

===== Physical/Chemical Properties =====

HCC:N1

Boiling Pt:B.P. Text:212F,100C

Melt/Freeze Pt:M.P/F.P Text:NA

Decomp Temp:Decomp Text:NP

Vapor Pres:18MM @68F

Vapor Density: