View NSN Online: https://aerobasegroup.com/nsn/3040-01-067-7976

## 

Product ID:REDCO RNAW MSDS Date:01/01/1999 FSC:3040 NIIN:01-067-7976 Status Code:A MSDS Number: CKKYD === Responsible Party === Company Name: REDDAWAY MFG CO INC Address:32 EUCLID AVE City:NEWARK State:NJ ZIP:07105-4515 Country:US Info Phone Num:201-589-1410 Emergency Phone Num:973-589-1410 CAGE:2H328 === Cont ractor Identification === Company Name: REDDAWAY MFG CO INC Address:32 EUCLID AVE Box:City:NEWARK State:NJ ZIP:07105-4515 Country:US Phone:201-589-1410 CAGE:2H328 **Company Name:WHEELER BROS INC** Address:384 DRUM AVE Box:737 City:SOMERSET State:PA ZIP:15501-0737 Country:US Phone:814-443-7000 CAGE:55683 Company Name: WHEELER BROTHERS INC Address: INDUSTRIAL PARK, DRUM AVE Box:737 City:SOMERSET State:PA ZIP:15501-2136 Country:US Phone:814-445-9641 Contract Num: DLA750-92-C-0367 CAGE:2B144

=================

Composition/Information on Ingredients ====================================
Ingred Name:FIBERGLASS CAS:65997-17-3 OSHA PEL:15 MG/M3 ACGIH TLV:10 MG/M3
Ingred Name:FULLY CURED PHENOLIC RESIN
======================================
Health Hazards Acute and Chronic:ACUTE: N/A. CHRONIC: POSSIBLE DERMATITIS OF THE SKIN. Effects of Overexposure:POSSIBLE DERMATITIS OF THE SKIN. APPROVED DUST RESPIRATOR SHOULD ALWAYS BE WORN WHEN CUTTING OR GRINDING.
======================================
First Aid:WASH SKIN WITH SOAP AND WATER. USE HAND CREAM TO MOISTURIZE SKIN.
======================================
Fire Fighting Procedures:USE USUAL FIRE FIGHTING PROCEDURES. Unusual Fire/Explosion Hazard:NONE
======================================
Spill Release Procedures: CLEAN UP AS ANY NON-HAZARDOUS MATERIAL.
======================================
Respirato ry Protection:USE APPROVED RESPIRATORY MASK TO PROTECT FROM DUST WHEN CUTTING OR MACHINING Ventilation:LOCAL EXHAUST-IF DESIRED. MECHANICAL EXHAUST-IF DESIRED. Protective Gloves:TO AVOID SKIN IRRITATION. Eye Protection:ALWAYS WHEN CUTTING OR DRILLING. Work Hygienic Practices:WASH HANDS AFTER USING. Supplemental Safety and Health
======================================
HCC:N1 Appearance and Odor:YELLOWISH TO GOLDEN, NO ODOR.
======================================

activity Data ===========

Stability Indicator/Materials to Avoid:YES Conditions to Avoid Polymerization:WILL NOT OCCUR.

Waste Disposal Methods: DISPOSE AS INERT WASTE.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this informa tion to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.