View NSN Online: https://aerobasegroup.jp/nsn/3439-00-350-1427

Product ID:SILVER SOLDER FLUX NO. 601 MSDS Date:05/25/1995 FSC:3439 NIIN:00-350-1427 Status Code:A MSDS Number: CLMLL === Responsible Party === Company Name: R & D METALS AND CHEMICALS INC Address:201 PERIMETER PK SUITE C Box:22533 City:KNOXVILLE State:TN ZIP:37922-2233 Country:US Т nfo Phone Num:865-531-6065 / FAX: 865-531-2044 Emergency Phone Num:865-531-6065 CAGE:56406 === Contractor Identification === Company Name: R & D METALS & CHEMICALS, INC Address:201C PERIMETER PARK Box:22533 City:KNOXVILLE State:TN ZIP:37922-2233 Country:US Phone: 423-531-6065 / FAX: 423-531-2044 Contract Num:SP0490-96-D-41080 CAGE:56406

Ingred Name:POTASSIUM FLUOROBORATE CAS:14075-53-7 RTECS #:ED2800000 Minumum % Wt:30. Maxumum % Wt:45. ACGIH TLV:2.5 MG/M3

Ingred Name:DIPOTASSIUM TETRABORATE CAS:1332-77-0 Minumum % Wt:15. Maxumum % Wt:25. ACGIH TLV:5 MG/M3

Ingred Name:BORIC ACID CAS:10043-35-3 RTECS #:ED4550000 Minumum % Wt:15. Maxumum % Wt:30. ACGIH TLV:10 MG/M3

Ingred Name:POTASSIUM FLUOBORATE CAS# 14075-53-7 Minumum % Wt:7. Maxumum % Wt:15. ACGIH TLV:2.5 MG/M3

Health Hazards Acute and Chronic:1. ACUTE OVEREXPOSURE: SALIVATION, COUGHING, C
HOKING & CHILLS. 2. CHRONIC OVEREXPOSURE: MAY CAUSE WEIGHT LOSS, BRITTLE BONES, ANEMIA, WEAKNESS & STIFF JOINTS.
Effects of Overexposure:1. ACUTE OVEREXPOSURE: SALIVATION, COUGHING, CHOKING & CHILLS. 2. CHRONIC OVEREXPOSURE: MAY CAUSE WEIGHT LOSS, BRITTLE BONES, ANEMIA, WEAKNESS & STIFF JOINTS.
Medical Cond Aggravated by Exposure:ANY WEAKNESS OF THE LUNGS, KIDNEYS OR LIVER WILL BE AGGRAVATED.

First Aid:INHALAT ION: REMOVE FROM CONTAMINATED AREA. EYES: WASH THOROUGHLY WITH WATER AND CALL A PHYSICIAN. SKIN: WASH THROUGHLY WITH WATER. INGESTION: DRINK WATER OR MILK AND CALL PHYSICIAN.

Flash Point:NONE Extinguishing Media:NOT NEEDED Fire Fighting Procedures:NORMAL CAUTION WHEN DEALING WITH FLUX CHEMICALS.

Unusual Fire/Explosion Hazard:WILL RELEASE BORON TRIOXIDE FUMES UPON DECOMPOSITION.

====== Accidental

Release Measures ===============

Spill Release Procedures: CLEAN UP PASTE AND FLUSH REMAINING MATERIAL WITH LOTS OF WATER. Handling and Storage Precautions: DO NOT STORE IN GLASS OR PORCELAIN CONTAINERS. AVOID CONTACT WITH EYES, SKIN AND CLOTHING. WASH THOROUGHLY AFTER HANDLING. Other Precautions: KEEP CONTAINERS AWAY FROM EXCESSIVE HEAT. Respi ratory Protection: NIOSH APPROVED RESPIRATOR IN ABSENCE OF PROPER VENTILATION. Protective Gloves: RUBBER OR PLASTIC COATED. Eye Protection: SAFETY GOGGLES. Other Protective Equipment: RUBBER APRON. Supplemental Safety and Health TRADE NAME AND SYNONYMS: SILVER SOLDER FLUX NO. 601. CHEMICAL FAMILY: SILVER BRAZING PASTE FLUX. HCC:N1 Spec Gravity:1.6 (H2O=1) Evaporation Rate & amp; Reference:0.3 Solubility in Water:MODERATE А ppearance and Odor:WHITE ODERLESS PASTE Percent Volatiles by Volume:30 Stability Indicator/Materials to Avoid:YES GLASS OR PORCELAIN. Stability Condition to Avoid: EXCESS HEAT. Hazardous Decomposition Products: B203 FUMES, K8F4. Waste Disposal Methods: DISPOSE IN ACCORDANCE WITH LOCAL STATE EPA **REGULATIONS.** Disclaimer (provided with this information by t

he compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.