View NSN Online: https://aerobasegroup.com/nsn/3439-00-121-5441

J.W. HARRIS CO., INC. (UNIBRAZE CORP.) -- SAFETY SILV 72 -- 3439-00-121-5441

Product ID:SAFETY SILV 72 MSDS Date:01/01/1987 FSC:3439 NIIN:00-121-5441 MSDS Number: BCZSQ === Responsible Party === Company Name: J.W. HARRIS CO., INC. (UNIBRAZE CORP.) Emergency Phone Num:513-891-2000 CAGE:27911 === Contractor Identification === Company Name: J. W. HARRIS CO., INC. Addre ss:10930 DEERFIELD ROAD Box:City:CINCINNATI State:OH ZIP:45242-4110 Country:US Phone:513-891-2000 CAGE:27911

Ingred Name:SILVER (SARA III) CAS:7440-22-4 RTECS #:VW3500000 Fraction by Wt: 72% OSHA PEL:0.01 MG/M3 ACGIH TLV:0.1 MG/M3; 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:COPPER (SARA III) CAS:7440-50-8 RTECS #:GL5325000 Fraction by Wt: 28% OSHA PEL:0.1MG/M3 FUME/1 DUST ACGIH TLV:0.2MG/M3 FUME; 9192 EPA Rpt Qty:5

======================================
Effects of Overexposure:COPPER FUME MAY CAUSE METAL FUME FEVER.SHORT TERM SYMP-METAL TASTE IN MOUTH,DRY IRRIT (SEE SUPP DATA
======================================
First Aid:REMOVE FROM DUST OR FUME EXPOSURE. IF BREATHING HAS STOPPED,PERFORM ARTIFICIAL RESPIRATION. SUMMON MEDICAL AID IMMEDIATELY.
======================================
Flash Point:NONFLAMMABLE Extinguishing Media:NONFLAMMABLE Fire Fighting Procedures:NONFLAMMABLE Unusual Fire/Explosion Hazard:(NONFLAMMABLE) OPEN FLAME & SPARKS CAN IGNITE COMBUSTIBLES,SEE ANSI/ASC Z49.1-1983 SECTION 6.
======================================
Spill Release Procedures:NOT APPLICABLE.
======================================
 Handling and Storage Precautions:READ & UNDERSTAND MFR'S INSTRCTNS & PRECAUTIO NARY LABEL ON PRODUCT.SEE AMERICAN NATIONAL STD Z49.1,,SFTY IN WELDING&CUTTING,&OSHA PUB 2206 (29CFR1910) Other Precautions:POSS USED W/FLUORIDE TYPE FLUX.IF APPLIC,CONSIDER FLUX FUME IN HAZ EVAL. HAZ DECOMP:IF FLUX COATED ROD,INCLUDE BORIC ACID (BORON OXIDE,TLV=10MG/CUM,PEL=15MG/CUM);FLUORIDES,TLV&PEL=2.5MG(F)/CUM
========= Exposure Controls/Personal Protection ====================================
Respiratory Protection:NIOSH/MSHA APPROVED RESPIRABLE FUME RESPIRATR/AIR SUPPLIED RESPIRATR

V

entilation:ENOUGH VENT,LOC EXHAUST AT FLAME TO KEEP FUMES&GASES < TLV'S Protective Gloves:WELDER'S GLOVES Eye Protection:FILTER LENS-PROPER SHADE# Other Protective Equipment:ARM PROTECTORS,APRONS,HATS,SHOULDER PROT,DARK STURDY CLOTHES Supplemental Safety and Health THROAT W/COUGH,SHORT BREATH,NAUSEA,FEVER,ACHE,CHILL.PULMONARY IRRIT/PNEUMOCONIOSIS POSS W/LONG TERM EXP TO WELD FUME,GAS,DUST.FUME IRRIT MAY AGGRAVATE LUNG ILLNESSES.PRIM EXP ROUTE-FUME INHAL.

HCC:N1

Appearance and Odor:SOLID WIRE/ROD.ROD POSS COAT W/CHEM FLUX-BLUE/OTHR

Hazardous Decomposition Products:SILVER (METAL & SOLUBLE CMPDS),COPPER (FUME),(SEE OTHR PREC)

Waste Disposal Methods:WASTE DISPOSAL MUST BE IN ACCORDANCE W/FEDERAL,STATE & LOCAL REGULATIONS.

Disclaimer (provided with this

information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.