View NSN Online: https://aerobasegroup.jp/nsn/6850-00-291-0963

Product ID:O-L-298B MSDS Date:01/01/1985 FSC:6850 NIIN:00-291-0963 **MSDS Number: BDVKS** === Responsible Party === **Company Name: PHOENIX PLASTICS INC** Address:215 S 23RD ST City:PHOENIX State:AZ ZIP:85034-2503 Country:US Emergency Phone Num:617-542-7341 CAGE:06372 === Contractor Identification === Company Name: PHIPP S PRODUCTS CORP Address:186 LINCOLN ST SUITE 502 Box:City:BOSTON State:MA ZIP:02111-2403 Country:US Phone:OUT OF BUSINESS CAGE:86511 Company Name: PHOENIX PLASTICS INC Address:215 S 23RD ST Box:City:PHOENIX State:AZ ZIP:85034-2503 Country:US CAGE:06372

Ingred Name:SOLVENTS Fraction by Wt: 1000% ACGIH TLV:300 PPM

Effects of Overexposure:SEVERE EYE IRRITANT,

DRYING SKIN. XS INHALE=HEADACHE, DIZZINESS & NAUSEA.

======================================
First Aid:EYE:FLUSH W WATER. SKIN:WASH W MILD SOAP & WATER & APPLY SKIN CREAM. INHALATION:REMOVE TO FRESH AIR & CALL PHYSICIAN;APPLY ARTIFICIAL RESPIRATION IF NECESSARY.
======================================
Flash Point:102F, 39C TCC Lower Limits:0.7 Upper Limits:6.0 Fire Fighting Procedures:WATER SPRAY, CO2, FOAM, DRY CHEM
==== =================================
Spill Release Procedures: FLUSH W WATER INTO RETAINING AREA OR CONTAINER. AVOID EXPOSURE TO SPARKS, FIRE OR HOT METAL SURFACES.
======================================
Handling and Storage Precautions: KEEP AWAY FROM HEAT, SPSRKS & OPEN FLAME. USE W ADEQUATE VENTILATION. AVOID PROLONGED OR REPEATED SKIN CONTACT.
======================================
Respiratory Protection:SELF-ONT BREATH APPARAT IF TLV EXCEEDED. Ventilation:LOCAL Protective Gloves:YES Eye Protection:YES Other Protective Equipment:EYE BATH & SAFETY SHOWER Supplemental Safety and Health BP:157-193C
======================================
HCC:F4 Boiling Pt:B.P. Text:315-380 Vapor Pres:2 Vapor Density:4.9 Spec Gravity:0.766 Evaporation Rate & amp; Reference:0.06/TOLUENE Solubility in Water:NEGLIGIBLE Appearance and Odor:WATER-WHITE

Percent Volatiles by Volume

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS. Stability Condition to Avoid:HEAT; SPARKS, OPEN FLAME & FIRE. Hazardous Decomposition Products:CO

Waste Disposal Methods:INCINERATE UNDER SAFE CONDITIONS OR DISPOSE OF IN ACCORD W LOCAL, STATE OR FED REG.

Disclaimer (provided with this information by the compiling agencies): This

information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.