View NSN Online: https://aerobasegroup.com/nsn/8010-00-468-4205

## 

Product ID:727002 PRIMER CIG C/N ALKYD CI FD

MSDS Date:01/01/1985

FSC:8010

NIIN:00-468-4205

MSDS Number: BDZNT
=== Responsible Party ===
Company Name:PRAXAIR INC
Address:39 OLD RIDGEBURY RD

Box:2153

City:DANBURY

State:CT

ZIP:06817-0001

Country:US

Info Phone Num:203-794-5782

Emergency Phone Num:

203-794-5782 CAGE:0LV01

=== Contractor Identification ===

Company Name: PRATT AND LAMBERT INC

Box:6027

City:CLEVELAND

State:OH

ZIP:44101-1027

Country:US

Phone:216-566-2902

CAGE:61196

Company Name:PRAXAIR, INC. Address:39 OLD RIDGEBURY RD

Box:City:DANBURY

State:CT

ZIP:06810-5113 Country:US

Phone:800-772-9247; 800-PRAXAIR


CAGE:0LV01

====== Composition/Information on Ingredients ========

Ingred Name: ZINC CHROMATE

CAS:13530-65-9 RTECS #:GB3290000 Fraction by Wt: 15% OSHA PEL:0.1 MG/M3

(CRO3) ACGIH TLV:0.01MG/M3(CR)A1;9192
ngred Name:ISOBUTYL ALCOHOL CAS:6168-86-1 RTECS #:MP9625000 Fraction by Wt: 8% ACGIH TLV:50PPM
ngred Name:ISOBUTYL ACETATE RTECS #:NP9100000 Fraction by Wt: 25% ACGIH TLV:150PPM
ngred Name:NAPHTHA ALIPHATIC Fraction by Wt: 8% ACGIH TLV:200PPM
ngred Name:ISOPROPYL ALCOHOL (SARA III) CAS:67-63-0 RTECS #:NT8050000 Fraction by Wt: 8% DSHA PEL:400 PPM/500 STEL ACGIH TLV:400 PPM/500STEL;9192
======================================
Effects of Overexposure:MAY CAUS BIRTH DEFECTS & REPRODUCTIVE & BLOOD DISORDERS.MAY BE ABSORB THRU THE SKIN.IRRIT OF NOSE(SU
First Aid:INHAL:REMOV FR EXPOS & PROVD FRESH AIR.SPLASH EYES,FLUSH IMMED W/LG AMTS OF WATR F/15 MIN.SPLASH SKIN,REMOV CONTAMINATED CLOTHING & WASH AFFECTED AREA W/WATR.INGSTION:DO NOT INDUC VOMTING.CONSULT A PH YSICIAN IMMED.
======================================
Flash Point:13F TCC-11C Extinguishing Media:CO*2,DRY CHEM,ALCOH FOAM.POLYMER FOAM PREF F/LARGE FIRES. Fire Fighting Precedures:SELF CONTAINED BREATH ARRADAT F/FIREMAL WATER
Fire Fighting Procedures:SELF-CONTAINED BREATH APPARAT F/FIREMN. WATR MAY BE INEFFECT Jnusual Fire/Explosion Hazard:KP CONTNRS TIGHT CLOS.ISOLAT FR HEAT ELECTR EQPMT,SPARK,OPN FLAM.DO NOT APPLY TO VERY HOT SURFACES.
======================================
Spill Release Procedures:REMOV ALL SOURC OF IGNIT(FLAMES,HOT SURFAC,ELECTRICAL,



Condition to Avoid:FIRES & HIGH TEMPERTURES
Hazardous Decomposition Products: CHROMATES & OXIDES OF CARBON
Conditions to Avoid Polymerization: DO NOT AD DRIERS OR REACTIVE CHEMS
W/O TECHNICAL SUPRVISION.

======= Disposal Considerations ===========

Waste Disposal Methods:DISPOSE IN ACCORD W/LOCAL,STATE & FEDERAL REGULATIONS.INCINERATE IN EPA APPRVD FACILITY.DO NOT INCINERATE CLOSED CONTAINERS.

Disclaimer (provided with this information by the compiling agenc ies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.