View NSN Online: https://aerobasegroup.com/nsn/5970-00-161-7422

THE P. D. GEORGE COMPANY -- STERLING Y-479 RED ELECTRICAL INSULATING VARNISH 07-293 -- 5970-00-161-7422

=========== Product Identification ==============

Product ID:STERLING Y-479 RED ELECTRICAL INSULATING VARNISH 07-293

MSDS Date:05/04/1993

FSC:5970

NIIN:00-161-7422

MSDS Number: BWNJS === Responsible Party ===

Company Name: THE P. D. GEORGE COMPANY

Address:5200 N 2ND ST

City:ST LOUIS

State:MO

ZIP:63147-3122

Cou ntry:US

Info Phone Num:314-621-5700/314-621-5701

Emergency Phone Num:314-622-8722

CAGE:97160

=== Contractor Identification ===

Company Name: THE P. D. GEORGE COMPANY

Address:5200 N 2ND ST

Box:City:ST LOUIS

State:MO

ZIP:63147-3122

Country:US

Phone:314-621-5700

CAGE:97160

======= Composition/Information on Ingredients ========

Ingred Name: ETHYL BENZENE (SARA III)

CAS:100-41-4

RTECS #:DA0700000 Fraction by Wt: 9.4%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:100 PPM ACGIH TLV:100 PPM/ 125STEL;9394

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:XYLENES (O-,M-,P- ISOMERS) (SARA III)

CAS:1330-20-7

RTECS #:ZE2100000 Fraction by Wt: 40.20%

Other REC Limits: NONE RECOMMENDED

**OSHA PEL:100 PPM** 

ACGIH TLV:100 PPM/150STEL;9394

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name: IRON OXIDE

CAS:1309-37-1

RTECS #:NO7400000 Fraction by Wt: 12.51%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:10 MG/M3 (FE)

ACGIH TLV:5MG(FE)/M3FUME,B2;94

Ingred Name: COBALT COMPOUNDS

Fraction by Wt: 0.

22%

Other REC Limits: NONE RECOMMENDED

=========== Hazards Identification ==========================

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:YES OSHA:NO

Health Hazards Acute and Chronic:INHAL:LUNG INJURY.SKIN:PROLONG/REPEAT CONTACT CASUE MODERATE IRRIT, DEFAT, DERM.EYE:VAP IRRIT.DIRECT CONTACT CAUSE MODERATE IRRIT W/CORNEAL INJURY.SKIN ABSORPTION:HARMFUL.INGEST:HARMFUL.CAUSE MOUTH/THRO AT/GASTROINTESTINAL TRACT IRR

 $IT, NAU, VOMIT, DIARR. ASPIRATION\ OF\ MATL$ 

INTO LUNGS CAUSE CHEM PNEUITIS WHICH CAN BE FATAL.

Explanation of Carcinogenicity:PER MSDS:CARCINOGENICITY:IARC:YES, NTP:NO, OSHA:NO.

Effects of Overexposure:REPEATED EXCESSIVE EXPOSURE TO PRODUCT MAY CAUSE CENTRAL NERVOUS SYSTEM,LIVER, AND KIDNEY EFFECTS & RESPIRATORY OR EYE IRRIT.

Medical Cond Aggravated by Exposure: SKIN CONTACT MAY AGGRAVATE AN EXISTING DERMATITIS.

First Aid:INHAL:REMOVE TO FRESH AIR. EYE:IMMED FLUSH W/PLENTY OF WATER FOR @LEAST 15MINS. CONSULT PHYSICIAN. SKIN:IMMED FLUSH W/SOAP & PLENTY OF WATER FOR @LEAST 15MINS. REMOVE CONTAMIN CLOTHING/SHOES. CONSULT PHYSICIAN. INGEST:CONSULT PHYSICIAN. NEVER GIVE ANYTHING BY MOUTH TO UNCONSCIOUS PERSON.

============= Fire Fighting Measures ===============

Flash Point:81.0F,27.2C

Lower Limits:1

Upper Limits:NO DATA

Extinguishing Media: CARBON DIOXIDE, DRY CHEMICAL, FOAM,

VAPORIZING LIQ TYP

EXTINGUISHING AGENTS.WATER SPRAY(FOG)EFFECTIVE W/FPT>100F.

Fire Fighting Procedures:REMOVE IGN SOURCES.KEEP PEOPLE AWAY & UPWIND.H2OSPRAY MAYBE INEFFECTIVE-SPREADS FIRE.FOG NOZZ PREFER.COOL CLSD CNTNR W/H2O.WEAR SCBA & PROT CLOTHING.

Unusual Fire/Explosion Hazard:STRAIGHT WATERSTREAM SPREADS FIRE.VAP ACCUM WILL FLASH/EXPLO IF IGN.CNTRN MAY BURST EXPLO IF OVERHEATED.EMPTY CNTNR ALSO FIRE/EXPLO HAZ DUE TO RESIDUE VAPORS.

======== Accidental Releas e Measures =============

Spill Release Procedures:REMOVE ALL IGN SOURCES.PROVIDE ADEQUATE VENTILATION.AVOID BREATH VAP.SHUT OFF SOURCE OF SPILL W/O RISK.USE NON-SPARKING TOOLS.ABSORB W/INERT ABSORBANT MATL.DISPOSE OF IN ACCORDANCE WITH APPLICABLE REG ULATIONS.

=========== Handling and Storage ================

Handling and Storage Precautions:DO NOT STORE >120F.KEEP CLOSURE TIGHT/CNTNR UPRIGHT TO PREVENT LEAKAGE.STORE DRUM OUT OF SUNLIGHT/AWAY FROM H

EAT/SPARKS/FLAME.STORE IN WELL VENTI AREA

Other Precautions:DRUMS/PAILS SHOULD BE GROUNDED WHEN BEING EMPTIED.NEVER USE PRESSURE TO EMPTY.DRUM NOT PRESSURE VESSEL.DO NOT PUNCTURE/DRAG/SLIDE CNTNR.EMPTIEE CNTNR MAY RETAIN HAZ RESIUDE/EXPLO VAP.KEEP AWAY FROM HE AT/SPARKS/FLAMES.DO NOT CUT/WELD(SUPPLE)

===== Exposure Controls/Personal Protection ========

Respiratory Protection: WEAR APPROPRIATE PROPERLY FITTED ARESP(NIOSH/MSHA APPROVED) DURING & AFAT APPLICATION

**UNLESS AIR** 

MONITORING DEMONSTRATES THAT VAPO/MIST LEVELS ARE BELOW APPLICABL LIMITS.FOLLLOW RESP MFG'S DIRECTIONS F OR RESP USE.

Ventilation:PROV GEN DIL/LOC EXHA VENTI IN VOL/PATTERN TO KEEP AIR CONTAMIN CONC