View NSN Online: https://aerobasegroup.jp/nsn/6850-01-398-2398

CANON INC -- 92291A, P170 TONER CARTRIDGE FOR HP LASERJET IIISI, -- 6850-01-398-2398

Product ID:92291A, P170 TONER CARTRIDGE FOR HP LASERJET IIISI,

MSDS Date:11/15/1990

FSC:6850

NIIN:01-398-2398

MSDS Number: BXQJC === Responsible Party === Company Name: CANON INC

Address:30-2 SHIRMOMARUKO 3 CHROME

City:OMTA-KU, TOKYO

Country:JA

Info Phone Num:516-328-5600

Emergenc

y Phone Num:516-328-5600

CAGE:EO274

=== Contractor Identification === Company Name:CANON INC

Address:30-2 SHIMOMARUKO 3-CHOME, OHTA-KU

Box:City:TOKYO

Country:JA

Phone:03-3758-2111/516-328-5600(USA)

CAGE:EO274

Company Name: HEWLETT-PACKARD CO, CORPORATE HQ

Address:3000 MINUTEMAN RD

Box:City:ANDOVER

State:MA

ZIP:01810-1032 Country:US

Phone: 404-648-8754/FAX: 800-947-3299

CAGE:28480

Company Name:TONER ETC Address:124 HERITAGE AVE Box:City:PORTSMOUTH

State:NH ZIP:03801 Country:US

Phone:800-370-8663

603-431-3624 CAGE:0YL79

======= Composition/Information on Ingredients ========

Ingred Name: STYRENE ACRYLATE COPLOYMER

Fraction by Wt: 45-55%

Other REC Limits: NONE RECOMMENDED

Ingred Name: IRON OXIDE

CAS:1317-61-9

Fraction by Wt: 45-55%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:10 MG/M3 ACGIH TLV:5 MG/M3

Ingred Name: AMORPHOUS SILICA

CAS:112945-52-5 RTECS #: VV7310000 Fraction by Wt: 0.5-2%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:6 MG/M3 ACGIH TLV:10 MG/M3

== Hazards Identification ===========

LD50 LC50 Mixture:PRODUCT'S LD50 (ORAL RAT) WAS NOT STATED

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic: ACUTE-TONER POWDER IS NOT ACCESSIBLE UNTIL THE CARTRIDGE IS FORCED TO BE BROKEN. INHALATION:TONER POWDER IS FINELY DIVIDED SOLID. DO NOT BREATHE THE DUST. EYE:NO SPECIFIC HAZARD IS KNOWN TO CANON. HOW EVER, ANY MATERIAL THAT CONTACTS THE

EYE MAY BE IRRITATING. SKIN:LOW HAZARD FOR INDUSTRIAL HANDLING. CHRONIC-NO DATA.

Explanation of Carcinogenicity: NO CARCINOGEN OR POTENTIAL CARCINOGEN, ACCORDING TO IARC, NTP, OSHA REGULATION & EC DIRECTIVE.

Effects of Overexposure:MFR GAVE NO INFORMATION ON MSDS.

Medical Cond Aggravated by Exposure:MFR GAVE NO INFORMATION ON MSDS.

First Aid:EYE CONTACT:FLUSH W/PLENTY OF WATER. SKIN CONTACT:WASH W/SOAP & WATER

======================================
Flash Point:NON FLAMMABLE Extinguishing Media:CARBON DIOXIDE, WATER, DRY CHEMICALS Fire Fighting Procedures:NONE Unusual Fire/Explosion Hazard:THIS MATERIAL, LIKE MOST ORGANIC MATERIAL IN POWDER FORM, IS CAPABLE OF CREATING A DUST EXPLOSION.
======== Accidental Release Measures ==========
Spill Release Procedures:NO TONER SPILLAGE OCCURS IN NORMAL OPERATION OR HANDLING. IF IT SHOULD OCCUR, AVOI D INHALATION OF THE DUST. SWEEP MATERIAL ONTO PAPER OR COLLECT IT. Neutralizing Agent:MFR GAVE NO INFORMATION ON MSDS.
======================================
Handling and Storage Precautions:KEEP AWAY FROM STRONG OXIDIZING AGENTS. KEEP OUT OF REACH OF CHILDREN. Other Precautions:NONE
====== Exposure Controls/Personal Protection =======
Respiratory Protection:NONE REQUIRED. Ventilation:USE GENERAL VENTILATION SHOULD BE SUFFICIENT. Protective Gloves:NONE REQUIRED Eye Protection:NONE REQUIRED Other Protective Equipment:NONE REQUIRED Work Hygienic Practices:MFR:? HMIS:USE GOOD INDUSTRIAL HYGIENE PRACTICES. MINIMIZE CONTACT & WASH THOROUGHLY AFTER HANDLING. Supplemental Safety and Health PRODUCT IS USED IN HEWLETT-PACKARD LASERJET IIISI. TONER IS CONTAINED IN A CARTRIDGE.
========= Physical/Chemical Properties ==========
HCC:V7 NRC/State Lic Num:NONE Melt/Freeze Pt:M.P/F.P Text:212F,100C Vapor Pres:NEGLIGI

BLE Spec Gravity:1.4-1.6

Evaporation Rate & Evaporation R

Solubility in Water: NEGLIGIBLE

Appearance and Odor:FINE POWDER; SLIGHT PLASTIC ODOR. COLOR NOT REPORTED.

Percent Volatiles by Volume: NEGLIG

======== Stability and Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZING AGENTS.

Stability Condition to Avoid:MFR GAVE NO INFORMATION ON MSDS.

Hazardous Decomposition Products:COMBUSTION WILL PRODUCE CARBON DIOXIDE & POSSIBLY

TOXIC CHEMICALS SUCH AS CARBON MONOXIDE.

Conditions to Avoid Polymerization: WILL NOT OCCUR.

======= Disposal Considerations ===========

Waste Disposal Methods:THIS PRODUCT IS CONSTRUCTED FROM PLASTICS & METALS. THE WASTE TONER COULD BE CONSIDERED AS PLASTIC WASTE. DISPOSAL SHOULD BE SUBJECT TO FEDERAL, STATE & LOCAL LAWS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.