

SIGMA CHEMICAL CO -- AMERLITE RESIN CHLORIDE FORM MACROPOROUS TYPE, IRA900 --  
6810-01-014-1027

=====  
Product Identification  
=====

Product ID:AMERLITE RESIN CHLORIDE FORM MACROPOROUS TYPE, IRA900

MSDS Date:01/01/1999

FSC:6810

NIIN:01-014-1027

Status Code:A

MSDS Number: CJSTF

=== Responsible Party ===

Company Name:SIGMA CHEMICAL CO

Box:14508

City:ST LOUIS

State:MO

ZIP:63178

Country:US

Info Phone Num

:314-771-5765

Emergency Phone Num:314-771-5765

CAGE:21076

=== Contractor Identification ===

Company Name:SIGMA CHEMICAL COMPANY

Address:3050 SPRUCE ST

Box:14508

City:ST LOUIS

State:MO

ZIP:63178

Country:US

Phone:314-771-5765

CAGE:21076

=====  
Composition/Information on Ingredients  
=====

Ingred Name:AMBERLITE RESIN CHLORIDE FORM MICROPOROUS TYPE

CAS:9050-97-9

Other REC Limits:N/K

OSHA PEL:N/K

OSHA STEL:N/K

ACGIH TLV:N/K

ACGIH STEL:N/K

=====  
Hazards Identif

ication =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:ACUTE: MAY BE HARMFUL BY INHALATION, INGESTION, OR SKIN ABSORPTION. MATERIAL IS IRRITATING TO MUCOUS MEMBRANES AND UPPER RESPIRATORY TRACT. CAUSES EYE AND SKIN IRRITATION. TO THE BEST OF MANUFACTURER' S KNOWLEDGE, THE CHEMICAL, PHYSICAL, AND TOXICOLOGICAL PROPERTIES HAVE NOT BEEN THOROUGHLY INVESTIGATED.

Effects of Overexposure:SEE HEALTH HAZARDS.

===== First Aid Measures =====

First Aid:INGESTION: WASH OUT MOUTH WITH WATER PROVIDED PERSON IS CONSCIOUS. CALL A PHYSICIAN. SKIN: FLUSH WITH COPIOUS AMOUNTS OF WATER FOR AT LEAST 15 MINUTES. REMOVE CONTAMINATED CLOTHING AND SHOES. CALL A PHYSICIAN. INHALATION: REMOVE TO FRESH AIR. IF BREATHING BECOMES DIFFICULT, CALL A PHYSICIAN. EYES: FLUSH WITH COPIOUS AMOUNTS OF WATER FOR AT LEAST 15 MINUTES. ASSURE ADEQUATE FLUSHING BY SEPARATING THE EYELIDS WITH FINGERS. CALL A PHYSICIAN.

===== Fire Fighting Measures =====

Autoignition Temp:=426.7C, 800.F

Extinguishing Media:CARBON DIOXIDE, DRY CHEMICAL POWDER, WATER SPRAY.

Fire Fighting Procedures:WEAR NIOSH APPROVED SCBA AND FULL PROTECTIVE EQUIPMENT .

===== Accidental Release Measures =====

Spill Release Procedures:WEAR NIOSH APPROVED RESPIRATOR, CHEMICAL SAFETY

GOGGLES, RUBBER BOOTS AND HEAVY RUBBER GLOVES. SWEEP UP, PLACE IN A BAG AND HOLD FOR WASTE DISPOSAL. VENTILATE AREA AND WASH SPILL SITE AFTER MATERIAL PICKUP IS COMPLETE.

===== Handling and Storage =====

Handling and Storage Precautions:DO NOT BREATHE VAPOR. DO NOT GET IN EYES, ON SKIN, ON CLOTHING. IRRITANT. KEEP CONTAINER CLOSED. STORE IN A COOL DRY PLACE. DRY IRON EXCHANGE RESINS EXPAND WHEN WETTED, WHICH MAY CAUSE COLUMN TO SHATTER.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NIOSH APPROVED RESPIRATOR.

Ventilation:MECHANICAL EXHAUST REQUIRED.

Protective Gloves:COMPATIBLE CHEMICAL-RESISTANT GLOVES.

Eye Protection:ANSI APPROVED CHEMICAL WORKERS GOGGLES .

Other Protective Equipment:ANSI APPROVED EMERGENCY EYEWASH AND DELUGE  
SHOWER .

Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING.

Supplemental Safety and Health

PHYSICAL/CHEMICAL PROPERTIES: PH: 5-9 AQUEOUS SLURRY.

=

===== Physical/Chemical Properties =====

Vapor Pres:17 MM @ 20C

Vapor Density: