View NSN Online: https://aerobasegroup.jp/nsn/5640-00-756-5866

WACO INC -- MARINE ACCOUSTICAL HULLBOARD -- 5640-00-756-5866

Product ID:MARINE ACCOUSTICAL HULLBOARD MSDS Date:12/04/1986 FSC:5640 NIIN:00-756-5866 Status Code:A MSDS Number: CLBCG === Responsible Party === **Company Name:WACO INC** Address:5450 LEWIS ROAD **City:SANDSTON** State:VA ZIP:23150 Country:US Info Phone Num:804-222-8440 Emergency Phone Num:000000000 CAGE:1B83 2 === Contractor Identification === Company Name:WACO INC Address:5450 LEWIS ROAD Box:City:SANDSTON State:VA ZIP:23150 Country:US Phone:804-222-8440 CAGE:1B832 Ingred Name: FIBROUS GLASS CAS:65996-61-4 ACGIH TLV:5 MG/M3 Ingred Name: PHENOLIC RESIN (CURED) CAS:25085-50-1 Ingred Name: ACRYLIC ADHESIVE CAS:79-10-7 RTECS #:AS4375000 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

======== Hazards Identification ========

=========
 Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:DIRECT EYE CONTACT WILL CAUSE MECHANICAL IRRITATION. SKIN CONTACT MAY CAUSE TRANSITORY MECHANICAL DERMITITIS. SKIN ABSORBTION DOES NOT OCCUR. Effects of Overexposure:REDNESS OF SKIN DUE TO MECHANICAL IRRITATION, WATERING EYES IN EVENT FIBERS GET IN EYES. Medical Cond Aggravated by Exposure:BRONCHIAL CONGESTION, HIGHLY ALLERGIC INDIVIDUALS.
======================================
es ====================================
First Aid:EYE CONTACT: FLUSH EYE WITH FLOWING WATER FOR AT LEAST 15 MINITUES. SKIN CONTACT: FREQUENT RINSING OF SKIN SURFACE TO REMOVE ACCUMULATED FIBERS WILL MINIMIZE IRRITATION.
======================================
Extinguishing Media:WATER, FOAM, CO2 OR CHEMICAL Fire Fighting Procedures:USE SCBA. FIBEROUS GLASS NON-FLAMMABLE. BINDER WILL PYROLIZE IN MAJOR CONFLAGRATION. Unusual Fire/Explosion Hazard:CO2, CO, AROMATIC H YDROCARBONS
======================================
Spill Release Procedures: VACCUM CLEAN DUST. USE A DUST SUPPRESSANT IF SWEEPING IS NECESSARY.
======================================
Handling and Storage Precautions: KEEP MATERIAL DRY AND MINIMIZE
GENERATION OF DUST. Other Precautions:WASH WORK CLOTHES SEPERATELY FROM OTHER CLOTHING TO PREVENT GLASS FIBER MIGRATION. RINSE WASHER THROUGHLY.
======== Exposure Controls/ Personal Protection ====================================
Respiratory Protection: A DISPOSABLE MASK DESIGNED FOR NUISANCE DUST SHOULD BE USED. Protective Gloves: RECCOMMENDED Eye Protection: GOGGLES Other Protective Equipment: WEAR LONG SLEEVED, LOOSE FITTING CLOTHING AND HEAD COVERING. Supplemental Safety and Health
======================================
Melt/Freeze Pt:-1371 1C, ######F

Melt/Freeze Pt:=1371.1C, ######F M.P/F.P Text:2500F Appearance and Odor:FIBEROUS GLASS BOARD COMPOSITE; NO APPRECIABLE ODOR Stability Indicator/Materials to Avoid:YES HYDROFLURIC ACID WILL DISSOLVE GLASS

Waste Disposal Methods: GENERALLY CLASSIFIED AS A NON-HAZARDOUS WASTE AND DISPOSAL MAY BE IN A LANDFILL FOR NON-CRITICAL MATERIALS. LOCAL REGULATIONS SHOULD BE CONSULTED.

Disclaimer (provided with this info

rmation by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.